IN RE INVESTIGATION OF AN ACCIDENT WHICH OCCUPRED ON THE HOPPHERM PACIFIC RAILWAY WEAR KANASKAT, WASH., ON MARCH 84, 1917.

May 25, 1917.

On March 24, 1917, there was a rear-end collision between a passenger train and a freight train on the Morthern Pacific Railway near Kanaskat, Wash., which resulted in the injury of 3 stocknes. After investigation of this accident, the Chief of the Division of Safety reports as follows:

Eastbound freight train No. 602 consisted of 55 care and a caboose, hauled by locamotive 1542, with helper locamotive 1605 out in 4 cars in advance of the emboose, and was in charge of Conductor Dancen and Raginemen Kane, with Enginemen Lyndahl in charge of the helper locamotive. Train No. 602 left Auburn, Wash., at 12.01 a. m. and at 1.22 a. m. passed Ravensdale, Wash., the last telegraph office, and a point about 4 miles west of the point of collision, being 52 minutes late at that time. While traveling at a speed of about 12 miles on hour the rear and of the train was struck by passenger train No. 518, the collision occurring about one mile west of Kanaskat.

Restbound passenger train No. 316 consisted of 6 cars, healed by locomotive 2186, and was in charge of Gonductor Medinimes and Engineens Deviscourt. It left Seattle, Wash., at 12.01 a. m., Ravenedale at 1.38 a. m., 3 minutes late, and at about 1.45 a. m. collided with the rear end of train No. 602, while traveling at a speed estimated to have been about 25 miles an hour.

The caboose of train No. 602, in which the injured stockmen were riding, was telescoped by the cer immediately sheed of it and demolished. The rear three cars of the freight train were devailed and damaged. Only slight damage was sustained by the locamotive of the passenger train and none of the equipment of that train was devailed.

This part of the Northern Pacific Railway is a single-track line and the movement of trains is rotected by an automatic block signal No. 880 is at the end of the passing track at Syrd, a small station 3.3 miles east of Kensaskat. This signal is located about 500 feet east of the western end of a curve to the right of 2 degrees and 10 minutes, this curve being 1,800 feet in length; the signal can be seen about three-fourths of a mile. There is them a curve to the left varying from two to six

degrees, the greater part of the ourve being 2 degrees. This ourse is about 4,550 feat in length. Automatic signal No. 846 is located on the outside of this curve at a point where the our vature is 2 degrees, and is about 5,000 feet east of signal No. 850. Signal No. 846 can be seen by enginemen a distance of about 150 feet and by firemon a distance of 800 feet. Following this curve there is 180 feet of tangent and then a curve to the right of 6 degrees. about 1,520 feet in length. About 300 feet east of the and of this curve is automatic signal No. 854, the distance between signal No. 846 and signal No. 834 being meerly 5,800 feet. The collision occurred on this last curve at a point about 300 feet from its eastern end or about 600 feet west of signal No. 854. The grade throughout practically all this territory is nearly I per cent. asomating for eastbound trains. At the time of the secicont a beavy snow was falling.

Engineran Kane stated that his train approached the west switch at Byrd, which is 2.5 miles from the point of collision, at 1.27 a. m., the speed at that time being about 25 miles an hour. He stated that the signals after passing Revensdale all indicated caution so that he knew there was a train immediately ahead of him. Upon approaching the signal between Byrd and Kamaskat, No. 846, it was found to be red and he reduced the speed preparatory to stopping, but the signal went to cention before his locomotive reched it. The train then proceeded toward the next signal. No. 534, and that was red. He had nearly brought his train to a stop when the signal changed to eaution. He thought it was about 1,38 or 1,39 a. m., when this signal was passed. He whistled out a fleg shortly after passing this signal, but said that he did not think this whistle signal could have been heard from the rear of the train. He sounded this signal because he knew that his train was alose to the time of train So. 518 and also because he would have to stop in order to head in on the passing track at Kemeaskat. He thought the collision occurred about 2 or 3 minutes after he had sounded this whistle signal, in which time his train had moved shead about 40 or 50 cer lengths. He thought the speed of his train at the time was about 8 or 10 miles an hour.

Firemen Montgomery verified the statements of Raginemen Kane as to whistling out a flag after passing signal No. 834. Shortly afterwards the train line was broken, due to the collision, and at that time he looked

at his watch and it was then 1.46 c. s.

Barinessa Lindahl of the belper locomotive stated that the train slowed down east of Byrd and on looking back he sew a yellow faces thrown off from the cabooset at this time he was about 400 or 500 feet east of eignal No. 850, near Byrd. He looked at his watch when the train started shead after stopping at signal No. 854 and it was 1.39 s. m. A short time efterwards be decided that be sould whistle out a flag, but on again looking back he saw the flagman get off with a white lentern. Soon he again looked best and saw trein No. 518 apposshing at a good rate of speed. apparently within three oar lengths of the ochoose and he told the firecan that he thought the passenger train was running the block signals and was going to collide with their train. The collision control at about this time. He further stated that he did not hear the engineers of the leeding locomotive whistle out a flag and he did not see any fusees thrown off other than the one thrown off just east of Byrd. So thought the socident occurred at about 1.43 a. m.

Conductor Dunces stated that just east of Byrd a 10minute yellow fuses was thrown off at abot 1.30 a. m. At about 1.55 a. m. the trein slowed down a little and he parscally threw off snother fuses somewhere east of signal No. 846 while soon afterwards the brakeman threw off a third Tuses. Conductor Duncam said that the train came almost to a stop and he thought it had stopped to head in at Kanaskat. He then west out on the rear end of the eaboose and rode there for 10 or 12 car lengths before he could discover his location. The flagman asked him if he should go back to flag and he looked at his watch and it was exactly 1.40 a. m. He instructed the flagmen to get off, which he did, taking with him torpodoes and red and white leaterns. The speed then increased from 4 miles am hour to 6 or 10 miles am hour and soon the flagmen was out of sight. Conductor Duncan said that he and the middle brakesen could hear the exhaust of the locomotive of train No. 316 as that train approached and they listened to beer the engineess of that trein shut off stem for the automatic signal. This, however, was not done so they listened for the enginessa to shut off steem when enswering the flagmen's signals. There was no answer, however, neither did they hear the explosion of any torpedoes and soon the headlight of the locametive healing train No. Dis appeared out of the out and Conductor Duncan said that he opened the caboose down and ealled to the stockmen to get off, at the seme time jumping from the rear platform. He did not look at his watch at that time, but thought it was about 1.45 a. m.. and said that the locomotive of train No. 518 was working steem when the collision occurred. He

thought his train moved about 1,200 or 1,400 feet between the time the flagman got off and the time of the collision. He had not heard the enginemen of his train whistle out a flag. He further stated that during the past 8 years be had been disciplined twice for failure to protect his train.

Flagman McCown of train No. 602 stated that the train slowed down east of Byrd and later slowed down again for the next signal, and he three off a burning fusee, this being 20 or 50 cer lengths beyond the point where the condustor had thrown off a fusee. Shortly afterwards he told the conductor that he had better get off and flag and secured his red lantern. The conductor looked at his watch and instructed him to get off, which he did. He stated that he started back with no fusees with him. He heard the passenger train approaches ing and placed one torpedo on the rail and then began to run toward the approaching train. He thought he went back 20 or 30 car lengths beyond the torpedo, being within 30 feet of the point where the last fusee had been thrown off, which was at that time burning. He kept giving stop signals and when the train passed him, traveling at a speed of about 50 miles on hour, he called to the engine over but did not see any one on the locamotive. He did not hear the locamotive explode the torpedo which he had placed on the rail. After the train passed he returned to the scene of the accident. He stated that he did not meet the flagman of the passenger train as he went back to flag. Be stated that he was back about 50 or 60 cer lengths from the rear of his train.

Middle Brakeman Love, of train No. 802, stated that the last fuses thrown off was thrown off by the flagman when the train slowed down for the signal west of Kanaskat. Then the train started sheed the conductor told the flagman to get off and the last he saw of the flagman the flagman was going back to flag. He did not look at his watch and did not hear any signals sounded by the engineers. He thought about 2 or 3 minutes elapsed between the time the flagman got off the train and the time the collision occurred.

Engineman Daviscourt, of train No. 515, stated that while passing through Byrd the water glass broken. He got off his seat box to shut the valve and found the fireman was also trying to do the same thing. He then got back on the seat box and found that he had passed signal No. 550 without secing its indication. He figured, however, that its most restrictive indication would be caution, incomuch as the preceding signal was clear. After the steam had been shut off from the mater glass he tried to see out of the window but could not on account of the heavy know blowing in his face. He then tried to see out of the front window but it was covered with moisture, probably due to the steam in the cab. As locamentive AlSS was not equipped with a clear vision window he had

to lean forward to wine off the front cab window and on doing so found that he could only see through the bottom part of it, the upper part being covered with mow. He then tried the water gauge cooks and found no water in the middle cook, but after finding water in the bottom each he sat down on the seat box and began to look for the next signal, No. 846, but did not see it. He stated that he did not see any flagman or notice the reflection of any fuses: neither did he hear any torpedoes. The first thing he sew was what seemed to him to be a dozen red lanterns and he then realized that he had passed another block signal without seeing its indication. He them attempted to shut off steam but on account of his hand being wet it slipped off the throttle, a slight delay thus being occasioned. After shutting off steem he applied the emergency air brokes but by that time the distance between the two trains was such that he could not prevent the collision. Engineers Deviscourt further stated that at no time while trying to shut off the steem from the water glass or while testing the water gauge socks did he reduce the speed of the train. He thought be was about I minute late passing Byrd but stated that he did not look at his watch until a short time after the collision and it was them 1.46 s. s. He further stated that at the time he was elecning off the front window, he did not realize that his train had passed the automatic signal. No. 846, but after the collision he figured out that this was the time when his trein passed that signal.

Pireness Evalues stated that after the veter glass broke he was busy trying to find the valve in order to shut off the steam and water. He thought it was about a minute from the time the glass broke until he had closed the valves and by this time the train had passed signal No. 850. He them becam to work on the fire as it had gotten vey low while he was fixing the broken rater glass valves and he was working on it from that time until the time the emergency air brakes were applied, the collision occurring before he had time to look up to see what was shead. He further stated that he had not noticed the reflection of any fusees or heard the explosion of any torpedoes. About one-half minute before the collision occurred he had looked at his watch and it was them between 1.45 and 1.46 a. m.

Conductor McMinimee, of train No. 318, stated that his train passed Byrd at 1.41 a. H. and ascording to his watch the sollision occurred at 1.44 a. H. About 6 or 8 minutes afterwards he saw Flagman McNown, of train No. 602, returning from flagging, carrying red and white lanterns in his hands. He also stated that Flagman Ringer of his train went back to flag and told him that he found a burning fuses.

Flagman Ringer stated that he started back to flag immediately after the collision and that he found a burning yellow fusee about 2,000 feet from the rear of his train, there still being about 4 inches of the fusee unburned, the fusee apparently having burned about 8 minutes. He thought it took him about 4 or 5 minutes to reach the point where he found this fusee and he said that he did not meet any flagman returning to the freight train.

Signal Inspector White, who was a passenger on train No. 318, stated that after dressing he left the ear and after looking at the wreakage went bank with a signal maintainer to examine and test the signals. The signal immediately in the rear of the wreakage, No. 846, was in the stop position while signal No. 850 was in the eaution position. Both of these signals were immediately tested and found to be working in proper order.

The direct cause of this accident was the failure of Enginemen Daviscourt of train No. 318 to observe and be governed by automatic block signal indications.

Engineers Daviscourt similated that he failed to observe the two automatic signals immediately preceding the point of accident which indicated caution and stop, respectively, this failure undoubtedly being due to the fact that he failed to reduce the speed of his train when circumstances arose which prevented him from seeing the signals. He know of the existence and location of these signals and there is no excuse for his failure to reduce the speed of his train to such an extent as to have enabled him to observe and be governed by the signal indications.

Enginemen Davisoourt was employed as a firemen in 1901 and promoted to enginemen in 1904. In 1906 he was suspended for 15 days for responsibility in connection with a collision and in 1907 was suspended for 15 days for derailing a locomotive. In 1916 he was suspended for 30 days for running against an opposing train without time table or train order rights.

Enginemen Devisoourt had been on duty about 2g hours after about 12 hours off duty.

In connection with the statement of Engineers Davissourt that his vision was obscured by steem on the inside of the eab windows as a result of the broken water glass and by the accumulation of snow on the outside of the eab windows, attention is directed to Rule No. 116-B of the Rules and Instructions for Inspection and Testing of Steem Locamotives and Tenders, which rule reads as follows:

"Road locomotives used in regions where showstorms are generally encountered shall be provided with what is known as a "clear vision" window, which is a window hinged at the top and placed in the glass in each front onb door or window. These windows shall be not less than 5 inches high, located as nearly as possible in line of the enginemen's vision, and so constructed that they say be easily opened or closed."

Locamotive 2186 was not equipped with a clear vision window in accordance with the Order of the Commission above referred to, and for this failure properly to equip the locamotive the operating officials of this road are responsible. Had locamotive 2186 been properly equipped with a clear vision window Engineman Daviscourt could have opened this window and the steam and accumulation of snow would not have prevented his seeing the automatic signals, as well as the fusees and the flagman's signals, and in all probability train No. 516 could have been brought to a stop in time to prevent the collision. Immediate steps should be taken by the officials of this road to see that their locamotives are equipped with such safety devices and appliances as are required by the various orders of the Commission in order that the safety of their employees and of the traveling public may be fully protested.